Home Inspection Report

of

Your adress

Your town

for

Client Name

on

08/09/12



Nour Mihaileanu

3225 Sunset Ln

Franklin Park, IL

773-983-9155

nm@homeinspectionestate.com

www.homeinspectionestate.com

IL Lic # 450.010998

SUMMARY

*SUMMARY of the items the inspector considers in need of immediate concern. All items below should be evaluated and repaired by a licensed professional. The full account of the home's condition, solely in the opinion of the inspector, including those which operate but may be nearing failure, is listed in the body of the report which is to be read carefully by the client. It is the client's decision as to what remedies are to be taken.

INSPECTION SUMMARY*

Address: Client Name

Your adress Your town

- 1. The gas was off at the time of the inspection and all the gas appliances and components, including the furnace, could not be tested. The AC condenser unit was not present or installed at the time of inspection. The heating unit is in need of service and evaluation by a HVAC professional prior to closing.
- 2. The exterior GFCI outlet on the West side is miss wired (open ground). The main electrical panel needs cleanup. A licensed electrician should evaluate and make all necessary corrections before closing.
- 3. The exterior drain cleanout access is obstructed by the house siding. The basement has no sump pump to protect it from water. The whirlpool in the master bathroom did not operate from the on/off switch button and the drain stop is defective. A licensed plumber should evaluate and make all necessary corrections prior closing.
- 4. Due to the visual condition of the roof, or in fact it could not be fully visible, I recommend having a licensed roofing contractor to evaluate it before closing.
- 5. The South sidewalk has settled and is a trip hazard.
- 6. The exterior floor drain cover by the basement door is damaged and it should be replaced. The drain tile opening on the South side should be sealed to avoid clogging. The exterior siding should have 6-8 inches clearance above grade to avoid moisture damage.
- 7. The basement bedroom window could not be opened. The upper level NE bedroom closet door needs adjustment.

Inspector: Nour Mihaileanu Lic. #450.010998 exp. 11/30/14 **Date:** 08/09/12

Home Inspection Report - 08/09/12

Your adress Your town

GENERAL

Age:50+ yearsType:Single familyMain entrance faces:WestWeather:DryTemp:80 + degreesBuyer Present:Yes

Status: Vacant



ROOF

Age:1-5 yearsVisibility:PartialLimited by:AccessibilityRoof Type:HipLayers:1Viewed from:Not Fully Visible

Roof Material: Asphalt

Visible Shingle Condition: Satisfactory

(Roofs may contain hidden defects that will not be seen today. If this is a concern, consult a professional.)

Due to the visual condition of the roof or the fact that it could not be fully viewed, I recommend it be professionally evaluated prior to the closing.

Valleys

Type: None

Roof Flashing

Type: Aluminum Visible Condition: Satisfactory

Vents

Type: Soffit Skylights

Count: 1 **Visible Condition:** Satisfactory

Plumbing Vents

Present? Yes **Visible Condition:** Satisfactory

Comments



EXTERIOR

Gutters/Downspouts

Type: Aluminum Visible Condition: Marginal

Siding

Type: Vinyl/brick Condition: Satisfactory

A board by board search was not performed.

Caulking

Exterior caulking has areas that need to be redone.

Trim/Soffit
Type: Metal

Condition: Satisfactory

Window Frames

Type: Metal

Storms/Screens: Yes

Areas of Wood Need

Normal maintenance

Exterior Electric

Type: Overhead GFCI: Yes Outlet: Yes

Operational: Yes

Unless otherwise noted, the exterior was inspected from the ground.



The exterior GFCI outlet on the West side is miss wired (open ground)

Entry Door

Condition: Satisfactory

Side Door

Condition: Satisfactory

Basement

Condition: Satisfactory

GROUNDS

Walks

Walks: Yes Type: Concrete Condition: Cracked

Front stoop/steps

Front stoop/steps: Yes Type: Concrete Condition: Satisfactory

Back stoop/steps

Back stoop/steps: Yes Type: Wood Condition: Satisfactory

Exterior Hand Rails

Exterior Hand Rails: Yes Type: Wood Condition: Satisfactory

Patio

Patio: Yes Type: Concrete Condition: Marginal

Porch

Porch: Yes Type: Wood Condition: Satisfactory

Landscaping-Foundation

Negative grade: East: Yes

West: Yes North: No South: No

Foundation Protections

Type: Gutters & drain tiles Condition: Marginal

Water is destructive and any home without 3 foundation protections - gutters, positive grade and drain tiles - is subject to water penetration.



The drain tile opening on the South side should be sealed to avoid clogging.

GARAGE

Type: Detached # of Cars: 2

Garage Door #1

Type: Metal Condition: Satisfactory Automatic Opener: Yes

Opener Operational: Yes **Safety Reverse:** Operates

Roofing

Type: Same as the house Condition: Satisfactory

Siding

Type: Vinyl Condition: Satisfactory

Trim

Type: Same as the house Condition: Satisfactory

Floor

Type: Concrete

Condition: Not Fully Visible

Window

Satisfactory

Door

Door Springs: Satisfactory **Side Door:** Satisfactory

Garage Structure

Condition: Satisfactory Firewall: NA

Sill Plate: Not fully visible

Electrical

Outlet: Yes GFCI: Yes Operational: Yes



The garage was not fully visible and not fully inspected due to storage or clutter.

PLUMBING

The plumbing, all or in part, needs professional evaluation prior to closing.

Supply: Public Supply Lines: Not visible Condition: Satisfactory

Waste: Not Fully Visible Shutoff Location: Basement Pressure: Satisfactory

The water in the home was run for: 20 minutes

Sanitary Pump:NAPlumber Needed?:NoWasher:NoneDryer:None

Plumbing leaks always begin slowly and take time to fully reveal themselves. We are limited to the amount of water we can run during an inspection. The passage of time between the inspection and the closing makes it crucial that all fixtures be operated and checked at the time of the walkthrough.

DWV: Not Fully Visible **Condition:** Not Fully Visible **Discharge:**

(The underground pipes, inside and out, were not visible and not inspected)

Water Heater(s)

<u>Main</u>

Brand: Richmond Type: Electric Capacity: 50 Gal.

Age: New

Recommendation:

Condition: Satisfactory



ELECTRICAL SERVICE

Main

Location: Basement Amps: 100 Volts: 120

(The # of amps is an approximation. Consult an electrician for

Type: Breakers the exact number.)


Service
Conductor:

Aluminum Branch Wiring: Copper Sheathing: Conduit

Issues: See summary page

Recommendation:

The Electrical System, all or in part, needs professional evaluation prior to closing.



HEATING

Gas to the home is shut off and no tests were done.

This HVAC system is in need of professional servicing and cleaning prior to the closing

Main

Make: Heil Age: 1-5 years Condition: Clean

Fuel: Gas Distribution: Ductwork Type: Forced Air

Vent pipes: Satisfactory
Heat Exchanger: Not fully visible
Filter: Disposable

Humidifier: None


Furnace operation:

When turned on by thermostat:

Is shut down

The Heating/cooling System needs professional evaluation prior to closing.

The heat exchanger should be checked for cracks no matter what age



BATHROOMS

Master Bathroom

Ceilings/walls:

Condition: Satisfactory

Floors:

Condition: Satisfactory

Doors:

Condition: Satisfactory

Ventilation/Heating:

Window in bathroom? Yes

Window Condition: Satisfactory **Window Screens:** Satisfactory

Ventilation Fan: Operational Visible Heat Source: Yes

Sink:

Condition: Satisfactory

Plumber Needed? No

Toilet Condition:	Satisfactory								
Tub/Shower Condition:	Satisfactory		Jacuzzi:		oes not operate				
Drainage / Water Drainage:	r Pressure Satisfactory		Water Pressure:		Satisfactory				
Electrical Outlet:	Yes	GFCI:	Yes	Operation	nal:	Yes			
Main Bathroom									
Ceilings/walls: Condition:	Satisfactory								
Floors: Condition:	Satisfactory								
Doors: Condition:	Satisfactory								
Ventilation/Heati Window in bathr Window Condition Window Screens: Ventilation Fan:	oom? on:	S	Tes Satisfactory Satisfactory Operational	Visible H	eat Source:	Yes			
Sink: Condition: Plumber Needed?	?			Satisfac No	etory				
Toilet Condition:	Satisfactory								
Tub/Shower Condition:	Satisfac		etory J a		zzi:	None			
Drainage / Water Drainage:	Pressure Satisfa		Water Pro	essure:	Satisf	actory			

Electrical

Yes

GFCI:


Outlet:

Electrical Outlet:	Yes	GFCI:	Yes	Operational:		Yes			
Basement Bathroon	<u>n</u>								
Ceilings/walls: Condition:	Satisfactory								
Floors: Condition:	Satisfactory								
Doors: Condition:	Satisfactory								
Ventilation/Heating Window in bathroo	_	No		W 71 H 46		V			
Ventilation Fan: Sink:		Ope	rational	Visible Heat Sour	ce:	Yes			
Condition: Plumber Needed?				Satisfactory No					
Toilet Condition:	Satisfactory								
Tub/Shower Condition:		Satisfactory		Jacuzzi:	None				
Drainage / Water I Drainage:	Pressure Satisfacto	ory	Water Press	sure:	Satisfactory				

Yes

Operational:

Yes



BEDROOMS

Master Bedroom

Ceilings/walls: Satisfactory
Floors: Satisfactory

Doors: Satisfactory Windows: Satisfactory Screens: Satisfactory

Visible heat source: Yes

Electrical

Switches: Yes Outlets: Yes

Northeast Bedroom

Ceilings/walls: Satisfactory
Floors: Satisfactory

Doors: Satisfactory Windows: Satisfactory Screens: Satisfactory

Visible heat source: Yes

Electrical

Switches: Yes Outlets: Yes

Ceilings/walls: Satisfactory

Floors: Satisfactory

Doors: Satisfactory Windows: Satisfactory Screens: Satisfactory

Visible heat source: Yes

Electrical

Switches: Yes Outlets: Yes

Attic Bedroom

Ceilings/walls: Satisfactory

Floors: Satisfactory

Doors: Satisfactory Windows: Satisfactory Screens: Satisfactory

Visible heat source: Yes

Electrical

Switches: Yes Outlets: Yes

Basement Bedroom

Ceilings/walls: Satisfactory

Floors: Satisfactory

Doors: Satisfactory Windows: Does not Operate Screens: Satisfactory

Visible heat source: Yes

Electrical

Switches: Yes Outlets: Yes



The basement bedroom window could not be opened.

ROOMS

Living Room

Location:Main FloorCeilings/walls:SatisfactoryFloors:Satisfactory

Doors: NA Windows: Satisfactory Screens: Missing/damaged

Visible heat source: Yes

Electrical

Switches: Yes Outlets: Yes

Dining Room

Location:Main FloorCeilings/walls:SatisfactoryFloors:Satisfactory

Doors: Satisfactory Windows: Satisfactory Screens: Satisfactory

Visible heat source: Yes

Electrical

Switches: Yes Outlets: Yes



Living room window screen is damaged.

KITCHEN

Kitchen

Ceilings/walls: Satisfactory
Floors: Satisfactory

Doors: NA Windows: Satisfactory Visible heat source: Yes

Counters: Satisfactory Cabinets: Satisfactory

Faucet: Satisfactory

Pipes: Do not leak Drainage: Adequate Pressure: Adequate

Microwave: Operates:

Refrigerator: Yes Operates: Yes

Range: Yes Operates: Not tested

Oven: Yes Operates: Not able to test

Dishwasher: Yes **Operates:** Yes

Fan: No Disposal: No

Electrical

Outlets: Yes GFCI: Yes Operates: Yes

(The appliances were tested solely to see if they operate and not for the quality of their performance.)



INTERIOR BASICS

Windows

Operation: Satisfactory

Material:

Vinyl

Type: Single Hung

Insulated Glass

Problems:None Visible

Screens: Satisfactory

Stairs: Satisfactory

Whole House Fan


Operates:

NA

Carbon monoxide and smoke detectors are required in every home and new detectors should be installed at the time of the closing

BASEMENT

Inside **Stairs:** Satisfactory Access: **Foundation Walls** # of Unusual Cracks: 0 Not visible Type: **Flooding Signs** None Visible Structural (Without a drain tile system, all basements/crawl spaces are subject to water seepage.) **Supports** Not Fully Visible **Condition:** Not Fully Visible % visible: 0 Type: Size: NA Not Fully Visible **Material: Beams** % visible: Type: Not Fully Visible **Condition:** Not Fully Visible 0 **Floors** Concrete/Tile **Condition:** Satisfactory Type: **Posts** Type: Not Fully Visible **Condition:** Not Fully Visible % visible: 0 **Basement Moisture** Dry today Windows Windows: Satisfactory **Screens:** Satisfactory **Basement Drainage Sump Pump:** No Floor Drain: Yes Full **Finished Basement:** 0 Foundation, walls, floors, and floor joists: % Visible: The basement walls, floor, and ceiling could not be examined without removing materials which is prohibited. Thus, no judgement is being made about the conditions present here.




Finished basement.



North side tuckpointing should be redone.



The exterior drain cleanout access is obstructed by the house siding.



The South sidewalk has settled and is a trip hazard.



The exterior floor drain cover by the basement door is damaged and it should be replaced.



The AC condenser unit was not present or installed at the time of inspection.